CORRECT

DEPENDING ON LOCATION
OF LAST PULLEY,
EITHER OF THESE
COULD BE CORRECT.

IMPORTANT:
MAKE SURE THE CABLE PASSES
STRAIGHT OFF THE LAST PULLEY
THROUGH THE CABLE GUIDE.

INCORRECT

NOTICE CABLE IS INCORRECTLY LOOPED
AROUND THE CABLE RETAINER SCREW

INCORRECT

NOTICE CABLE GUIDE IS BACKWARDS
CAUSING INCORRECT CABLE ALIGNMENT